

# Service Experience of MAN B&W Two-stroke Diesel Engines

Stig B. Jakobsen  
Senior Manager  
Low Speed – Operation

# Disclaimer



All data provided on the following slides is for information purposes only, explicitly non-binding and subject to changes without further notice.

# Service Experience of MAN B&W Two-stroke Diesel Engines



- **Total Cost of Ownership for Large Marine Propulsion Engines**
- **New ECS Software for ME/ME-C Engines**
- **Operation on Low Sulphur Fuels**
- **Low Load Operation Update 2011**
- **Cylinder Condition Update – New Engine Types**
- **G-type Engines – Short Introduction**

# Service Experience of MAN B&W Two-stroke Diesel Engines



- **Total Cost of Ownership for Large Marine Propulsion Engines**
- New ECS Software for ME/ME-C Engines
- Operation on Low Sulphur Fuels
- Low Load Operation Update 2011
- Cylinder Condition Update – New Engine Types
- G-type Engines – Short Introduction

# Total Cost of Ownership of Marine Propulsion Engines



## Example: Large Bore MAN B&W 2-Stroke Engine

	40% Load Average	80% Load Average
<b>Investment Cost</b>	100%	100%
<b>Operating Cost/year:</b>		
- Fuel	100%	200%
- Cylinder Oil	1.3%	2.6%
- System Oil	0.3%	0.3%
- Overhaul Cost	0.5%	0.5%
- Spare Parts	3.5%	3.5%
<b>Scrapping</b>	?	?



# Total Cost of Ownership of Marine Propulsion Engines: **Investment Costs**



## Constant Focus on First-Cost Cost-Down Example: Low Force Exhaust Valve



Potential First Cost Saving: 200,000 USD for a 12K98ME/ME-C Engine

# Total Cost of Ownership of Marine Propulsion Engines: **Operating Costs, Fuel**



## Fuel Costs:


- Extremely Dominating over the Lifetime of a Propulsion Plant
- In Tier 2 version ME-engines have 2-3 g/kWh lower SFOC when comparing to corresponding MC-engines
- Background for introduction of the fuel optimised Tier 2 engines (dot2 engines) with SFOC 1-2 g/kWh lowered
- Reason for increased focus on low load and part load tuning
- Autotuning

**However: In many cases the traditional split of costs between ship-owners and charterers limits the optimisation of the propulsion plant (as example WHR systems)**

# Total Cost of Ownership of Marine Propulsion Engines: **Operating Costs, Cylinder Oil**



- Combustion Chamber optimised for low SLOC
- Alpha Lubricator with ACC secures minimum SLOC



**Recent Service Experience:  
MAN B&W 2-stroke engines maintain  
stable cylinder condition with minimum SLOC at low  
load both with and without T/C cut out**



# Total Cost of Ownership of Marine Propulsion Engines: **Operating Costs, Overhaul&Spares**



Service Letter SL09-509/SBJ

MAN Diesel



However please note our  
SL07-483/HRR concerning  
**Condition Based Overhaul**

**For Large Bore Engines:**  
Overhaul intervals for Dry Cargo Vessels can be largely  
extended in general to more than 32,000 hours

**Dock to dock without major overhauls is possible for Tankers**

Action code: **WHEN CONVENIENT**

## **Guiding Overhaul Intervals** Updated Tables

SL09-509/SBJ

April 2009

### **Concerns**

Owners and operators of MAN B&W  
two-stroke diesel engines.

Type: ME/ME-C, ME-B and MC/MC-C

# Total Cost of Ownership of Marine Propulsion Engines: **Operating Costs, Overhaul&Spares**



Service Letter SL09-509/SBJ

MAN Diesel



## ME/ME-C engines Guiding overhaul intervals and expected service life

Component	Overhaul interval (hours)	Expected service life (hours)		Remarks
Main hydraulic pump	32,000	Engine lifetime		Check and replace hydrostatic bearings at overhaul. Check and replace cylinder set and piston if required.
Proportional valve for main hydraulic pump		20,000		Replace valve after 20,000 hours
Pressure relief valve for main hydraulic pumps	40,000	Engine lifetime		Replace sealings at overhaul
Exhaust valve actuator	32,000	Engine lifetime		Replace static sealing rings at overhaul.
FIVA valve	32,000	64,000		Check and replace if required
Fuel valve	8,000 - depending on fuel quality	Valve nozzle Spindle guide	16,000 16,000	Check and replace if required
Fuel oil pressure booster	32,000 - based on engine observations	64,000 Replace or recondition		Change piston rings on hydraulic piston and suction valve at overhaul.

Action code: **WHEN CONVENIENT**

## Guiding Overhaul Intervals Updated Tables

SL09-509/SBJ  
April 2009

### Concerns

Owners and operators of MAN B&W two-stroke diesel engines.

Type: ME/ME-C, ME-B and MC/MC-C

# Damage to Pilot Valves on FIVA's During Commissioning Period



## Service Test of Bosch Rexroth FIVA:

### Ship 1: same unit


-After 20h	3,32 l/min
-After 723h (same cylinder as 20h)	1,27 l/min
-After 743h	3,87 l/min

### Ship 2:

-After 2893h	4,60 l/min
--------------	------------

### Ship 3:

-After 5000h	3,33 l/min
--------------	------------





Leakage: delivered  
with max 1,3 l/min

# Damage to Pilot Valves on FIVA's During Commissioning Period





- Ship 1
- Painting, rubber and ??




Wear on pilot valve

- Ship 2
- Painting, metal particles and ??



# Damage to Pilot Valves on FIVA's During Commisioning Period






# Service Experience of MAN B&W Two-stroke Diesel Engines



- Total Cost of Ownership for Large Marine Propulsion Engines
- **New ECS Software for ME/ME-C Engines**
- Operation on Low Sulphur Fuels
- Low Load Operation Update 2011
- Cylinder Condition Update – New Engine Types
- G-type Engines – Short Introduction

## Multi Purpose Controller (MPC) Failures



# ME Engines in Service Software Improvements



## **ME-ECS 0905-8 compared to ME-ECS 0510-12**

Commissioning Screen for HCU, Tacho and HPS

Trouble Shooting Screens for HCU and HPS

Data logger for HCU and HPS

Export of HCU and HPS data logger data to Excel

ECS isolation monitoring and alarms

Electrical noise monitoring and alarm

Alarm improvements, grouping of related alarms

# Trouble Shooting Screens for HCU



Maintenance ▶ Troubleshooting 2011-03-14 12:59:12

HCU HPS HCU Events HPS Events

Cylinder: 1 2 3 4 5 6 7 8 9 10 11 12

MPC Mode  
Test

Fuel Plunger Position

CH-31	Max. - Min.	Stroke
---		

Exhaust Valve Position

CH-34	Max. - Min.	Stroke
---		

MPC CCU-1

J34 J70 J20 J31 J30

FIVA Amplifier OK  
CH-20 ON

FIVA Valve Control  
CH-70 -0.5 V

FIVA Amp. J91 J90

FIVA Position FB  
CH-30 19.4 mA

FIVA Actual Current  
CH-33 -0.0 A

Hyd. Oil  
---

WARNING: Operating with low hydraulic press. might damage accumulators.

WARNING: Operating without fuel oil pressure might damage fuel booster.

Fuel Plunger Inject Return

Exhaust Valve Open Close

Start Cyclic Test

Alarms...  
Engine...  
Auxiliaries...  
Maintenance ▶  
System View I/O Test  
Invalidated Inputs  
Network Status  
Function Test  
Trouble-shooting  
Admin...  
Power Off ⓘ  
Access Chief


# Data Logger for HCU



Triggered by event



# Data Logger for HCU



# Service Experience of MAN B&W Two-stroke Diesel Engines



- Total Cost of Ownership for Large Marine Propulsion Engines
- New ECS Software for ME/ME-C Engines
- **Operation on Low Sulphur Fuels**
- Low Load Operation Update 2011
- Cylinder Condition Update – New Engine Types
- G-type Engines – Short Introduction

# MAN B&W 2-stroke Marine Engines: Controlling SO<sub>x</sub> by Burning Clean Fuel



## Challenges burning clean fuel:

- Low viscosity of gas oil causing starting difficulties
- Low lubricity causing fuel pump seizures
- High “cat-fines” content especially seen on SECA-fuels
- Cylinder Oils for low or no sulphur fuels




# MAN B&W 2-stroke Marine Engines: Controlling SO<sub>x</sub> by Burning Clean Fuel



- Majority of distillate fuels has viscosities in the range of 2.5 – 4 cSt.
- Low viscosity may cause starting difficulties and problems operating low load
- Low viscosity may cause poor lubricity causing fuel pump seizures


Number of bunkers (distillates)  
(5702 data sets)



source reference: DNVPS

Temperature of MGO to ensure viscosity below recommended 2 cSt

Fuel temp vs Viscosity



# MAN B&W 2-stroke Marine Engines: Controlling SO<sub>x</sub> by Burning Clean Fuel



Shipboard Experiences with  
Low Sulfur Distillate Fuel Oil



Unintended Consequences

PREPARED BY  
Maritime Safety Unit  
Jeff Cowan  
Mike Coyne

## Challenges burning clean fuel:

### LOSS OF PROPULSION INCIDENTS

## 2004 – 2010

(as of Oct 1, 2010)

<i>Port</i>	<i>2004</i>	<i>2005</i>	<i>2006</i>	<i>2007</i>	<i>2008</i>	<i>2009</i>	<i>2010</i>
<b>San Francisco</b>	15	11	10	10	12	37	17
<b>Los Angeles / Long Beach</b>	8	12	6	14	14	28	10
<b>San Diego</b>	0	1	3	0	0	0	2
<b>Santa Barbara</b>	0	1	0	0	0	2	1
<b>Humboldt</b>	0	0	1	0	0	0	0
<i>Total per year</i>	23	25	20	24	26	67	30

<i>Monthly Totals in 2009</i>		
Month	Total LOPs	Fuel Switching Related
Jan – June 2009	21	9
Jul-09	13	6
Aug-09	8	4
Sep-09	9	5
Oct-09	8	3
Nov-09	3	2
Dec-09	5	4
<b>Totals</b>	<b>67</b>	<b>33</b>
<i>Monthly Totals in 2010</i>		
	Total Loss of Propulsion Incidents	Loss of Propulsion - Fuel Switching Related
Jan-10	5	1
Feb-10	3	0
Mar-10	3	2
Apr-10	2	0
May-10	4	0
Jun-10	2	0
Jul-10	3	2
Aug-10	1	0
Sep-10	7	1
<b>Totals</b>	<b>30</b>	<b>6</b>



# MAN B&W 2-stroke Marine Engines: Controlling SO<sub>x</sub> by Burning Clean Fuel



Shipboard Experiences with  
Low Sulfur Distillate Fuel Oil



Unintended Consequences


PREPARED BY  
Maritime Safety Unit  
Jeff Cowan  
Mike Coyne

## LOSS OF PROPULSION INCIDENTS

January 2004 to August 2011

Contradiction to previously presented data

Number of incidents



Source: US Coast Guard

# MAN B&W 2-stroke Marine Engines: Controlling SO<sub>x</sub> by Burning Clean Fuel




The new CARB rules have lead to an increase in cases of starting difficulties after change over to distillate fuel.

However, such cases is “just” the result of worn fuel pumps, due to neglect of qualified performance check.

Fuel pumps must be overhauled before the index has increased 10% in relation to test bed condition.

**Fuel pump high pressure leakage  
mainly generated at cut off holes:**




**MAN Diesel prepares a Service Letter for “re-learning”  
of performance check to judge fuel pump wear**

# MAN B&W 2-stroke Marine Engines: Controlling SO<sub>x</sub> by Burning Clean Fuel



Challenge of Low sulphur HFO; the lower sulphur the more cat-fines



Source: DNVPS database of 1,012 analysis results (from 1 October – 10 November 2007)

# MAN B&W 2-stroke Marine Engines: Controlling SO<sub>x</sub> by Burning Clean Fuel




## Replica technique:


- The density of cat-fines was found extremely high, with up to 3,000 / cm<sup>2</sup>. Acceptable level is below 200 / cm<sup>2</sup> !
- The sizes vary from 5µm to 15 µm with a smaller number of "big" cat-fines in a range of 20 – 25 µm.
- This is a result of inefficiently working centrifuges.



# MAN B&W 2-stroke Marine Engines: Controlling SO<sub>x</sub> by Burning Clean Fuel



## Sulphur neutralization (additive control)





# MAN B&W 2-stroke Marine Engines: Controlling SO<sub>x</sub> by Burning Clean Fuel



## Additive control at low sulphur running:

- How does over-additivation harm the cylinder condition?
- Over-additivation lead to mechanical- and chemical bore polish
- Bore polish lead to micro-seizures and latent risk of scuffing
- Running more then 1 - 2 weeks in SECA area, it is recommended to change to a lower BN cylinder oil (BN40 – 50 cylinder oil)



# MAN B&W 2-stroke Marine Engines: Controlling SO<sub>x</sub> by Burning Clean Fuel



**Extended CARB regulations will  
require BN12 – 20 Cylinder Oils!**

## ACC Cylinder Lubrication




Fig. 1: Recommended cylinder lubrication feed rate as a function of the fuel oil sulphur content for selected lubricating oils (BN40-BN70)

# Service Experience of MAN B&W Two-stroke Diesel Engines



- Total Cost of Ownership for Large Marine Propulsion Engines
- New ECS Software for ME/ME-C Engines
- Operation on Low Sulphur Fuels
- **Low Load Operation Update 2011**
- Cylinder Condition Update – New Engine Types
- G-type Engines – Short Introduction



# Low Load Operation

Operation down to 10% Engine Load  
Service Experience & Recommendations



# Low Load Operation Service Tests



## Low load tests

7K80MC-C	10% load	Sep. 2009	Container ship
9K98ME-C	20-22% load	Mar. 2008	Container ship
12K98MC-C	10% load	Oct. 2009	Container ship

## T/C cut out tests

12K98ME	swing gates, ABB T/C	Container ship
10K98MC-C	swing gates, MET T/C	Container ship
12K98MC	blind plates, MET T/C	Container ship
9K90MC-C	blind plates, MAN T/C	Container ship

# Low Load Operation Service Feedback



## Two Stroke Low Load Operation Inspection report template (SL09-511)

MAN Diesel

### Two Stroke Low Load Ope

The purpose of this report is to document the service experience engine load.

The reports should be used to op engine load up for cleaning of boi space, and with regard to cylinde The report should preferably be n 4 times a month. This could be re

Below items should as minimum

Date of inspection

Vessel name

IMO number

Engine Builder / Number

Engine Type:

Main engine running hours:

Load range [%]:

Pictures, as shown as examples, should be added.



**Inspection area #1:** The non-ret valves in the scavenging air recei should be photographed.  
*Comment:*


MAN Diesel



**Inspection area #3:** The drain line from the buffer spaces should be photographed.  
*Comment:*



**Inspection area #5:** The piston crown should be photographed.  
*Comment:*



**Inspection area #7:** The exh. valves should be photographed from the exh. gas receiver side  
*Comment:*

MAN Diesel



Picture examples from the turbochargers are not available, but in some cases it is possible to have a view of the nozzle ring and maybe the turbine blades from the exh. gas receiver side, through the safety grid. Please supply pictures from this if possible.

Information regarding operation, maintenance and observations during low load operation:

- During low load operation for longer periods, were there any changes in engine load in order to 'clean' the engine and exhaust gas ways?  
*Answer: aa*
- Was it necessary to increase the maintenance intervals during low load operation? (Cleaning of receivers, turbochargers, boilers ect.)  
*Answer: bb*
- If temperature indication is available after the boiler this should be reported in order to evaluate acid corrosion in the boiler and funnel.  
*Answer: cc*
- What was the specific cylinder lube oil consumption and was the level of cylinder lubrication satisfactory?  
*Answer: dd*
- Are the auxiliary blower running at the stated engine load?  
*Answer: ee*
- Were any changes made to temperature/viscosity of the HFO?  
*Answer: ff*
- Were any problems experienced during low load operation?  
*Answer: gg*
- Based on your experience, do you have any recommendation regarding low load operation?  
*Answer: hh*

A performance observation at the stated load and a full scavenge port inspection (picture report of all cylinders) would be expedient for the further evaluation; however this must be based on the available time and necessity judged by the crew.

# Low Load Operation Service Feedback



## Feedback reports (21)

1)	8S50MC	14% load	Container ship
2)	7L70ME-C	20-30% load	Container ship
3)	7L70ME-C	25-40% load	Container ship
4)	6S70MC-C	30-35% load	Bulk carrier
5)	7S70MC-C7	10% load	Tanker
6)	8K80ME-C	30% load	Container ship
7)	8K80ME-C	23% load	Container ship
8)	8K80ME-C	10% load	Container ship
9)	8K80MC-C	14-20% load	Container ship
10)	8K80MC-C	35% load	Container ship
11)	8K80MC-C	30-50% load	Container ship
12)	7L80MC	30% load	Container ship
13)	7K90MC-C	13-30% load	Container ship
14)	8K90MC-C	20-34% load	Container ship
15)	10K90MC	20-22% load	Container ship
16)	10K90MC	20% load	Container ship
17)	10K90MC	20% load	Container ship
18)	12K90MC	30% load	Container ship
19)	9K98MC-C	12-25% load	Container ship
20)	12K98MC-C	30% load	Container ship
21)	12K98MC	14-21% load	Container ship



## General experience from the tests:

- No significant change in fouling condition of exhaust gas ways
- Slightly increased fouling in scavenge air space
- Apparently too high cylinder oil feed rate at <25% load

# Low Load Operation Service Test



## **Service test (Sep. 2009):**

- Engine: 7K80MC-C (3 years old)
- Test duration: 3 days on 10% load
- No engine load up

## **Conclusion**

No significant change in fouling condition of exhaust gas ways

# Low Load Operation Service Test



Inspection after 1-day test



Inspection before test



Inspection after 3-day test



# Low Load Operation Service Test



Inspection after 1-day test



Inspection before test



Inspection after 3-day test



# Low Load Operation Service Test




Inspection after 1-day test



Inspection before test



Inspection after 3-day test






# Low Load Operation Service Test



Inspection after 1-day test



Inspection before test




Inspection after 3-day test



# Low Load Operation Service Test



Inspection after 1-day test



Inspection before test



Inspection after 3-day test





# Low Load Operation Service Test



Inspection after 1-day test



Inspection before test



Inspection after 3-day test



## Service feedback report (Oct 2009):

- Engine: 8K90MC-C (1 year old)
- Test duration: 21 days on 20-34% load
- Engine load up every second day to 75% load

## **Conclusion**

No significant change in fouling condition

# Low Load Operation Service Feedback



## Sample pictures:


Scavenge air receiver



# Low Load Operation Service Feedback



## Cylinder unit 1





# Low Load Operation Service Feedback



## Exhaust receiver / boiler top



### C/E's remark :

- Was it necessary to increase the maintenance intervals while slow steaming? (cleaning of receivers, buffer spaces, T/Cs, boilers, etc?)

*After 509 hrs of slow steaming we do not see the dire necessity of cleaning it. Did not find any abnormalities or signs of over-lubrication. Sludge amount in the corners and on the walls was normal.*

# Low Load Operation Service Feedback



## **Service feedback report (Jan 2009):**

- Engine: 8S50MC (17 years old)
- Retrofitted with Slide Fuel Valves
- Load: 15% load
- Engine load up every day (to 10,000 TC rpm)

## **Conclusion**

No change in fouling condition




# Low Load Operation Service Feedback



## Sample pictures:

### Scavenge air receiver



# Low Load Operation Service Feedback



## Cylinder unit 1





# Low Load Operation Service Feedback



## Exhaust receiver / boiler top



### C/E's remark :

- Did you experience any problems related to the slow steaming operation?  
*Answer: NO*

## Feedback from vessels

### General comment:

- No problems observed

### Comments on C/E's experience gained (from the 21 reports):

- engine load up considered essential
- less mechanical stress on engine is expected to have positive influence on maintenance of the engine
- more often cleaning of the scavenge air receiver
- boiler seems to be more clean
- more frequent cleaning of boiler and scavenge air space considered necessary
- Alpha lubes have too high feed rate <25% load
- too little fresh water production
- scavenge air space more dirty
- increased wet deposits in scavenge air receiver
- 4-day load up interval ok
- more soot in exhaust receiver and on boiler top.

# Low Load Operation Service Experience



## General recommendations

- Service letter: SL09-511
- Service letter: SL11-544
- Inspection report template

**Action code: WHEN CONVENIENT**

### Low Load Operation

10% to 40% Engine Load

SL09-511/MTS  
May 2009

#### Concerns

Owners and operators of MAN B&W two-stroke marine diesel engines.  
Type: MC/MC-C and ME/ME-C

#### Summary

Long-term low load operation down to 10% engine load is generally possible with appropriate precautions and without major modifications.  
For application with 3-4 turbochargers, MAN Diesel recommends installation of a turbocharger cut-out system.

**Action code: WHEN CONVENIENT**

### Low Load Operation

2011 Update

SL11-544/MTS  
June 2011

#### Concerns

Owners and operators of MAN B&W two-stroke marine diesel engines.  
Types: MC/MC-C and ME/ME-C/ME-B

#### Summary

Feedback on low-load operation from the operators has generally been positive. Only a few issues have emerged, but have been dealt with by few countermeasures.

MAN Diesel





#### Two Stroke Low Load Operation - Inspection report template

The purpose of this report is to define the necessary inspection areas in order to follow and document the service experience gained during continuous engine operation below 50% engine load.  
The reports should be used to optimise the low load operation procedures with regard to engine load up for cleaning of boiler and turbocharger, cleaning of scavenge and exhaust space, and with regard to cylinder lubrication optimisation.  
The report should preferably be made before and after the low load operation period, or 3 to 4 times a month. This could be reduced with experience and unchanged load pattern.

Below items should as minimum be noted and inspected:

Date of inspection	: 2000-01-01
Vessel name	: M/V xxxx
IMO number	: 90xxxx
Engine Builder / Number	: xxxx / xxxx
Engine Type:	: 12K98MC-C
Main engine running hours:	: 50000 Hours
Load range [%]:	: 22%

Pictures, as shown as examples, should be inserted in the report and relevant comments should be added.

	
Inspection area #1: The non-return valves in the scavenging air receiver should be photographed. Comment:	Inspection area #2: The buffer space area should be photographed. Comment:

**Operating at low engine load, below 40%, can create issues in relation to:**

- Cylinder lubrication
- Continuous operation of auxiliary blowers
- Increased stress on flap valves in scav. receiver




# Low Load Operation Service Experience



## Cylinder Lubrication

For engines with Alpha lubricators (lubrication as a function of engine load), significant savings can be made on cylinder lube oil consumption

80% RPM of MCR results in a reduction of 50%



# Super Slow Steaming (SSS) Service Experience



From SL11-544 – June 2011




Fig. 3: Alpha Lubricator feed rate algorithm

Easy Low Load Optimization for ME-Engines

## Cylinder Lubrication - Alpha Lubricators

During operation at low load it has been experienced that over-lubrication can happen, due to layout of lubricators.

### Countermeasures

- Retrofit of lubricator pistons with reduced diameter
- Modification of lubricator by reducing piston stroke

**Operating at low engine load, below 40%, can create issues in relation to:**

- **Cylinder lubrication**
- **Continuous operation of auxiliary blowers**
- **Increased stress on flap valves in scav. receiver**

# Service Experience of MAN B&W Two-stroke Diesel Engines



- Total Cost of Ownership for Large Marine Propulsion Engines
- New ECS Software for ME/ME-C Engines
- Operation on Low Sulphur Fuels
- Low Load Operation Update 2011
- **Cylinder Condition Update – New Engine Types**
- G-type Engines – Short Introduction



# 7K80ME-C9.1: Cylinder Condition



## Details, scavenge port inspection:

### Unit no. 1

Running Hours: 12157

Condition of piston and rings:

Good condition with no signs of abnormal wear.

Topland: Light deposits Ringland: Clean

Cermet coating thickness:	
Ring	Measurement: (µm)
1	367
4	247

Mo coating thickness, skirt:	
Area	Measurement: (µm)
Top part	232
Middle	344
Lower part	277

Liner: Excellent condition. WC still visible.

Cylinder oil dosage:

Flat rate test at 0.55g/kWh.



### Unit no. 3

Running Hours: 12157

Condition of piston and rings:

Good condition with no signs of abnormal wear.

Topland: Light deposits Ringland: Clean

Cermet coating thickness:	
Ring	Measurement: (µm)
1	349
4	240

Mo coating thickness, skirt:	
Area	Measurement: (µm)
Top part	326
Middle	474
Lower part	432

Liner: Excellent condition. WC still visible.

Cylinder oil dosage:

Flat rate test at 0.55g/kWh.




# 7K80ME-C9.1: Cylinder Condition



## Cylinder unit No. 3 running surface:

Cylinder unit No 3 was inspected and found in good condition. On this unit a test with soft delivery cylinder lubrication is active.


The liner surface was found to be smooth, with no indication of abnormal wear. The surface lamella structure appeared slightly corrosive with an open graphite lamella structure, as indicated on the photo below, taken in measuring point No. 2, manoeuvring side.




# 7K80ME-C9.1: Cylinder Condition



## Max. Liner Diameter Analysis MAERSK BOGOR HYUNDA-AA3093



# Cylinder Lubrication, Corrosion Control





# 6S80ME-C9.1

## Test Bed, October 2010






# Electrically Driven Hydraulic Power Supply (HPS)



# Electrically Driven Hydraulic Power Supply (HPS)





# 6S80ME-C9.1

## PMI AutoTuning



Data Acquisition Unit (DAU)




Pressure Sensor



## Reduction in fuel oil consumption / CO<sub>2</sub> emission

1 bar increase in average  $p_{\max}$   $\Rightarrow$  0.20-0.25 g/kWh decrease in fuel oil consumption



Pure  $p_{\max}$  level increase  
Potential 5-10 bar  
Potential 1-2.5 G/kWh

Balancing +  $p_{\max}$  level increase  
Potential additional 2-5 bar



Total potential 1.4 – 3.75 g/kWh

Gain also with engines already being  
operated within recommended limits

# 6S80ME-C9.1



## Overhaul Inspection after Prototype Shop Trial: Main Bearing no. 5





# Engines for Large Container Ships



# Recent Trend: S90ME-C for Container Vessels




## Order list for Large Container Vessels

No of Ships			Engine		Mark	Owner	Capacity TEU	Yard	Hull no	Eng. Builder
18			9 S	90 ME-C	8.1	A.P. Moeller	7.000	DSME	4214->	Doosan
4			9 S	90 ME-C	8.2	Zodiac	9.000	DSME-Mangalia	4090->	Doosan
3			9 S	90 ME-C	9.2	Bernard Schulte	9.000	Shanghai Jiangnang CHI	1066A ->	HHI EMD
3			9 S	90 ME-C	9.2	Costamare	9.000	Shanghai Jiangnang CHI	1068A ->	HHI EMD
6			9 S	90 ME-C	8.2	Bernard Schulte/Ofer	9.000	HSHI	S592 ->	HHI EMD
6			12 S	90 ME-C	9.2	OOCL	13.000	SHI	2002 ->	HHI EMD
8	+	17	10 S	90 ME-C	9.2	SEASpan	10.000	New Yangzi	2011-983 ->	CMD
7	+	10	9 S	90 ME-C	8.2	Costamare	9.000	Sungdong	4010 ->	HHI EMD
4			9 S	90 ME-C	8.2	MSC	9.000	Sungdong		HHI EMD
6			8 S	90 ME-C	8.2	Hamburg Sued	9.600	HHI	2521 ->	HHI EMD
12			10 S	90 ME-C	9.2	NOL	9.000	DSME	conversion from K98ME-C	Doosan
10			11 S	90 ME-C	9.2	NOL	13.800	HSHI	S630 ->	HHI EMD
Total			87 ships							


# S90ME-C8&9 – Outline



S90ME-C9




S90ME-C8



# 9S90ME-C8.1: Cylinder Condition



**Cylinder no. 1 at 1,803 hours: Excellent Condition**



# Service Experience of MAN B&W Two-stroke Diesel Engines



- Total Cost of Ownership for Large Marine Propulsion Engines
- New ECS Software for ME/ME-C Engines
- Operation on Low Sulphur Fuels
- Low Load Operation Update 2011
- Cylinder Condition Update – New Engine Types
- **G-type Engines – Short Introduction**




# Daily Fuel Oil Consumption 6S/G70MC/E types and versions



Daily fuel consumption at 70% load

SMCR 18660 KW 91 rpm, figures at 70% load




# Green Series of G-ME Engines



Layout diagrams of new Green series of G-ME engines  
Compared with existing Super long stroke S-ME engines

Potential fuel savings of 4-7%

Main engine  
SMCR power  
kW




# G80ME-C9.2



320,000 dwt VLCC  
Increased propeller diameter  
G80ME-C9.2

Propeller		3.7%
Engine		1.0%
Total		4.7%




# G70ME-C9.2



Propulsion  
SMCR power  
kW

175,000 dwt Capesize bulk carrier  
Increased propeller diameter  
G70ME-C9.2

Propeller		4.5%
Engine		2.0%
Total		6.5%





# Thank You for Your Attention!



All data provided in this document is non-binding. This data serves informational purposes only and is especially not guaranteed in any way. Depending on the subsequent specific individual projects, the relevant data may be subject to changes and will be assessed and determined individually for each project. This will depend on the particular characteristics of each individual project, especially specific site and operational conditions.